

LATEST VEHICLE CONCERN FIXES



Check Engine Light with DTC P2170-11	18-19 MY Discovery Sport, RR Evoque, E PACE
<u>Customer Voice:</u> – The Check Engine Lamp is on. <u>Technical Description:</u> – DTC P2170-11 is stored in the PCM. – The active exhaust valve can be heard to operate during start. <u>Status:</u> – We are investigating the role that ambient conditions play in setting this DTC. – SSM 74333 and SSM 74326 have been published which elaborate on the diagnostic steps to be performed for this DTC. – Updated PCM software has a revised DTC strategy which removes the restricted performance flag in order to reduce the impact to the customer. – Raise an EPQR for any vehicle exhibiting this condition and include results of all diagnostic steps performed. The vehicle can be released back to the customer.	 

