



Technical Journal

TITLE:

DTC IHU-B156C8F sets incorrectlyREF NO:
TJ 33285.3.0ISSUING DEPARTMENT:
Technical ServiceCAR MARKET:
United States and CanadaPARTNER:
3 US 7510 Volvo Car USAISSUE DATE:
2018-02-26STATUS DATE:
2018-03-12FUNC GROUP:
3930FUNC DESC:
**Equipment for entertainment
(radio/TV/VC**

Page 1 of 2

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234							2017-2017		0000001-0999999	201617-201716
235							2017-9999		0000001-0999999	201624-999952
236							2017-9999		0000001-0999999	201646-999952
238							2018-9999		0000001-0999999	201717-999952
246							2018-9999		0000001-0999999	201717-999952
256							2016-9999		0000001-0999999	201505-999952
536							2019-9999		0000001-0999999	201746-999952

CSC Customer Symptom Codes

Code	Description
1C	Service/repair/Administrative and Factory scheduled maintenance
2V	Technician information/Software/Vehicle communication/Not for warranty use
3L	Technician information/Repair information/Not for warranty use

VST Operation Number



DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
IHU	B156C8F	Permanent
IHU	B156C8F	Intermittent

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

IHU - Infotainment Head Unit

LVDS = Low Voltage Differential Signal

In some cases, the DTC IHU-B156C8F, *“Wide Angle Vision Module (WAM) LVDS. Bus Signal / Message Failures. Erratic”*, may be set in the IHU.

This DTC may be set incorrectly and can be treated as a ghost DTC if there is no customer symptom.

SERVICE:

For the cars in the header this DTC can be ignored as it doesn't affect any of the functions in the car. Do not perform any fault tracing or component replacement due to this DTC if there is no related customer symptom.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area “Vehicle Report” and sub concern area “Support not needed”, use function group 3930.