



Preliminary Information

PIT5671 SIR Light with B0081 SYM4B

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade Models	2007 - 2014	All	All	All	All
Chevrolet	Avalanche	2007 - 2013	All	All	All	All
Chevrolet	Silverado 1500	2007 - 2013	All	All	All	All
Chevrolet	Suburban	2007 - 2014	All	All	All	All
Chevrolet	Tahoe	2007 - 2014	All	All	All	All
GMC	Sierra 1500	2007 - 2013	All	All	All	All
GMC	Yukon Models	2007 - 2014	All	All	All	All

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Involved Region or Country	North America
Condition	Dealer may find after replacing the PPS Kit for other concerns, there is a B0081 SYM4B (Passenger Presence System Calibration Not Learned) set in the passenger presence (PPS) module. On Non Hybrid vehicles, the PPS Kit does not require rezeroing procedure, this is done by the supplier.
Cause	Supplier quality concern.

Correction:

Dealers are to contact SPAC and create a case to obtain qualified parts from the supplier. Do not contact TAC as they are unable to assist with getting qualified parts.

Version History

Version	1
Modified	04/12/2019 - Created on

