

Subject		Market
DTC U0110		USA
Service Category	Section	
Engine/Hybrid System	Hybrid/Battery Control System	
Applicability		
2017-2019 MY Highlander HV		

APPLICABLE VEHICLES

2017-2019

Highlander HV

CONDITION

Some vehicles may have a U0110 DTC.

RECOMMENDATIONS

If the vehicle matches this condition, please create a TAS case and contact TAS. If it's a Sunday or holiday, continue with diagnosis and repair, save all parts and details, contact TAS on the next available work day and review details with TAS engineer.

LINK REFERENCES

This Tech Tip does not contain any link references