

On-car analysis list from August 5th, 2019
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on 1429 and/or P0556	Customer states MIL-on (Must have P1429 and/or P0556 in the ECM and vacuum pump inoperative)
	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on P0197	Customer states MIL-on (Must have P0197 in the ECM with wiring damaged at oil level sensor)
	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on P0133	Customer states MIL-on (Must have P0133 in the ECM)
	ATLAS	19	3.6 (CDVC)	All	MIL-on P0116	Customer states MIL-on (Must have P0116 in the ECM) (untouched vehicles)
	ATLAS	19	3.6 (CDVC)	All	MIL-on P2097	Customer states MIL-on (Must have P2097 in the ECM) (untouched vehicles)
Body	Tiguan LWB	18-19	All	All	Sunshade Binding	Customer states the sunshade is binding/tearing/separating (untouched vehicles)
	Jetta	19	All	All	Door Module	Customer states "door warning light" on dash and/or locks, mirrors or window functions inoperative (untouched vehicles)
Electrical	Passat	17-19	All	All	Airbag light on B200000	Customer states airbag light on (Must have fault B200000 with symptom code 16712596) (untouched vehicles)