

On-car analysis list from August 28th, 2019
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on 1429 and/or P0556	Customer states MIL-on (Must have P1429 and/or P0556 in the ECM and vacuum pump inoperative)
	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on P0197	Customer states MIL-on (Must have P0197 in the ECM with wiring damaged at oil level sensor)
	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on P0133	Customer states MIL-on (Must have P0133 in the ECM)
	ATLAS	19	3.6 (CDVC)	All	MIL-on P0116	Customer states MIL-on (Must have P0116 in the ECM) (untouched vehicles)
	ATLAS	19	3.6 (CDVC)	All	Engine Oil Leak	Customer states engine oil leak (untouched vehicles)
	ATLAS	19	3.6 (CDVC)	All	MIL-on P2097	Customer states MIL-on (Must have P2097 in the ECM) (untouched vehicles)
Body	Tiguan LWB	18-19	All	All	Sunshade Binding	Customer states the sunshade is binding/tearing/separating (untouched vehicles)
	Jetta	19	All	All	Front Window Noise	Customer states front window(s) noisy during operation (untouched vehicles)
	Jetta	19	All	All	Door Module	Customer states "door warning light" on dash and/or locks, mirrors or window functions inoperative (untouched vehicles)