

Subject		Market
DTC B15A8 - DCM System Internal Failure		USA
Service Category	Section	
Audio/Visual/Telematics	Cellular Communication	
Applicability		
All Applicable Models		

APPLICABLE VEHICLES

2020	Camry	2020	Corolla Hatchback
2020	Camry HV		

CONDITION

Some 2020 model year Camry, Camry HV and Corolla Hatchback vehicles equipped with a DCM may exhibit a B15A8** DTC in history during PDS. This DTC can be triggered during the manufacturing and /or shipping process and does not indicate a problem with the vehicle. To simplify the diagnosis of this DTC, refer to the procedure below to prevent unnecessary parts replacement.

RECOMMENDATIONS

Is the DTC current or a history DTC?

- Current – Continue diagnosis via the appropriate Repair Manual.
- History – Clear the DTC

LINK REFERENCES

This Tech Tip does not contain any link references