

GPOP - Issue Review System

Part Number: 04893610A\$, 05281451A\$, 68428448A\$, 68432441A\$, 68292196A\$, 68338787A\$, 04893612A\$

Part Description: Idle Related Components

Issue Description: For concern of P0507 diagnostic trouble code, please verify the powertrain control module is at the latest software level prior to replacing any components related to P0507 diagnostics.
