



# Service Bulletin

Bulletin No.: 19-NA-204

Date: September, 2019

## INFORMATION

**Subject:** Information on Airbag Light On - False DTC C3373 Set

| Brand:  | Model: | Model Year: |      | VIN: |    | Engine: | Transmission: |
|---------|--------|-------------|------|------|----|---------|---------------|
|         |        | from        | to   | from | to |         |               |
| Pontiac | Vibe   | 2009        | 2009 |      |    |         |               |

|                            |                                                                                                                                                                                                                 |
|----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Involved Region or Country | North America                                                                                                                                                                                                   |
| Condition                  | Some technicians may find DTC C3373 Set.                                                                                                                                                                        |
| Information                | If the Tech2 displays DTC C3373, disregard and use Diagnostic for B1773 in SI.<br>⇒ Follow the diagnostic for DTC B1773 and if required per diagnostics, replace the passenger front seatbelt tensioner per SI. |

### Parts Information

No parts are required for this repair.

|          |                             |
|----------|-----------------------------|
| Version  | 1                           |
| Modified | Released September 05, 2019 |

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION