



Preliminary Information

PIP5685 P0128 Setting

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019 - 2020	All	All	4.3 LV3	All
GMC	Sierra 1500 (New Model)	2019 - 2020	All	All	4.3 LV3	All

Involved Region or Country	North America
Condition	A vehicle with a customer concern of a SES P0128.
Cause	Engineering is aware of the concern and is working on a repair.

Correction:

At this time clear the codes and do not replace the thermostat for this concern.

There will be a calibration released for the concern in this near future.

This PI will be updated when the calibration is released.

Version History

Version	1
Modified	10/23/2019 - Created on.

