

GPOP - Issue Review System

Part Number: 68438679A\$

Part Description: GRILLE, Active Shutter

Issue Description: When replacing Active Grille Shutter on vehicles built before April 10th, 2018 rearrange pin configuration in the AGS connector to MY 2019 configuration. Failure to do so will result in U11E9 Loss of Comm with AGS. Please view I-sheet in STAR parts for reference.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.