



SERVICE BULLETIN

Classification:	Reference:	Date:
AT15-015i	NTB15-086i	December 19, 2017

2013-2014 ALTIMA; MIL ON WITH DTC P0776, P1715 MAY HAVE HESITATION AND/OR LACK OF POWER

APPLIED VEHICLES: 2013-2014 Altima (L33) with 4-cyl engine only

This bulletin has been superseded to NTB16-110. Please discard previous versions of this bulletin.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.