



Tech Tips

TT 91-16-09


Date: May 20, 2016

2015 Golf, GTI, Golf R, Sportwagen, eGolf – MIB1, 2016-2017
Golf, GTI, Golf R, Sportwagon, eGolf, Passat, Jetta, CC,
Tiguan, Beetle, Beetle Convertible – MIB2- B201A Fault Stored
in MIB2 Infotainment System

November 4, 2016: Update to Model Year Applicability.

After replacing or updating a J794/5F module, a “B201A: Checking software version management” fault may store. To erase this fault, perform the following:


Under the Special Functions tab, run the “005F-Design status check/reset DTC memory” test plan.





Service Information

When the test plan reaches the step to “restart the Main-Unit via the Touch-Screen-Monitor, hold the radio’s power button down for 10 seconds to reboot the J794. Once the radio turns back on, select Complete/Continue.



Once the test plan ends, the B201A fault should clear.