

Subject		Market
MIL "ON" with P0AFC Set		USA
Service Category	Section	
Vehicle Interior	Meter/Gauge/Display	
Applicability		
2012-2015 Camry HV		

APPLICABLE VEHICLES

2012-2015

Camry HV

CONDITION

Customer may complain about a MIL "ON" condition with P0AFC.

RECOMMENDATIONS

1. Check for aftermarket antenna in trunk area such as CB radio antenna.
2. If aftermarket antenna is found in trunk area it may cause DTC P0AFC to set, move antenna to a different location.
3. If DTC is present and there is no aftermarket antenna being used near the trunk area, then follow repair manual procedure for DTC P0AFC.

LINK REFERENCES

4. [HYBRID / BATTERY CONTROL: HYBRID BATTERY SYSTEM: P0AFC-123; Hybrid Battery Pack Sensor Module; 2015 MY Camry HV \[09/2014 - ???????\]](#)