



Preliminary Information

PIT5610 Service Engine Soon with P050F set in History

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2018	All	All	All	All
Chevrolet	Traverse	2018	All	All	All	All
Involved Region or Country		North America & Export Regions				
Condition		Customer may comment that they receive a "Service Brake Assist Message" accompanied by Service Engine Soon and a P050F code being set in history.				
Cause		Issue may be caused by slight vacuum leakdown on brake apply during auto stops within a 10 minute period.				

Correction:

Check vacuum system for proper operation following SI procedure, repair any issues that are found. If vacuum system is operating properly, replace brake booster.

Note: Engineering is still investigating the root cause. DO NOT CALL GM Technical Assistant Center for an update. The PI will be updated to a bulletin once the final root is understood.

Parts Information

Description	Part Number	Quantity
Booster	23371176	1
Gasket	22895247	1
Seal	22895248	1

Warranty Information

Labor Operation	Description	Labor Time
2441730	Power Brake Booster Replacement	1.1

Version History

Version	1
Modified	Created on 4/11/2018

