

9002688

02/13/2013

MY07-12

D2, DD, DJ, DP, DC, DM, D1, DH, DR

GPOP - Issue Review System

Part Number: 68069384A\$, R8069384A\$, 68086182A\$, R8027067A\$, RL002012A\$

Part Description: Gasket, Cylinder Head Cover

Issue Description: Before replacing injectors for Diagnostic Trouble Codes P0201, P0202, P0203, P0204, P0205, and/or P0206, please make sure that the wiring loom and/or connector in the valve cover gasket is not the root cause to your concern. In addition, make sure that the wiring attaching nuts are torqued to their proper value.~
~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.