March 16, 2016 MY15, 16 D2, DD, DJ, DP

GPOP - Issue Review System

Part Number: 52029762A$, 52029760A$

Part Description: Urea tank shell

Issue Description: Trucks equipped with a 6.7L Cummins Turbo Diesel only; If vehicle comes in with a P207F DTC, record the following information to be shared with the engineer. ~

- All Active and Inactive P-Codes~
- Refractometer concentration~
- WiTech Concentration~
- WiTech Concentration Sensor Temperature ~
- Urea Tank Temperature~
- Urea Tank level when fault was set~
- Hydrocarbon reading~
- Known fill history before and after the fault was set~
- Recent weather conditions in the area~
- Actions Taken since vehicle had been brought to the dealership ~

Please contact Gary Pleyte at cell (248) 705-3567 with the above information. If you are unable to get a response within 15 mins, please continue with the repair according to the trouble tree for P207F.~

~_____
__~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.