



Subject		Market
Electronic Parking Brake Malfunction Indicator on Gauge Display		USA
Service Category	Section	
Brake	Parking Brake	
Applicability		
2018-2019 LC500		

APPLICABLE VEHICLES

2018-2019

LC500

CONDITION

Some 2018 – 2019 MY LC500 vehicles equipped with the Electronic Parking Brake (EPB) may have an EPB malfunction indicator on the MID display with DTC C13A8.

RECOMMENDATIONS

Confirm DTC C13A8 is currently in FFD and confirm if DTC was set during normal customer usage. Please confirm FFD and Data List of Tension Sensor 1 and 2 Voltage is captured.

If the condition of your vehicle matches the condition described on this document, create a TAS case and contact TAS and provide details prior to the repair. If it's a weekend or holiday continue with diagnosis and repair, save all parts and details, contact TAS on the next available work day and review details with TAS engineer.

LINK REFERENCES

This Tech Tip does not contain any link references