



Bulletin No.: PIT5623
Published date: N/A

Preliminary Information

PIT5623 Intermittent Service Traction Control System (TCS)/StabiliTrak Light With Dual Rear Wheels

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Express	2018	All	All	All	All
GMC	Savana	2018	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	R05
Condition	Intermittent Service Traction Control System (TCS)/StabiliTrak Light with dual rear wheels setting C0050 Sym0F
Cause	Engineering is currently investigating concern

Correction:

Do not attempt repairs for this concern. Engineering is aware of the concern and working on a field fix. This PI will be updated when the repair is available.

Version History

Version	1
Modified	Created on 6/26/2018



GENERAL MOTORS

© 2018 General Motors. All Rights Reserved.