

On-car analysis list from September 2nd, 2016
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Tiguan	15	All	All	MIL-on P013E	MIL-on fault P013E in the ECM
	Passat	16	1.8T (CPRA, CPKA)	All	MIL-on P0299	MIL-on with loose boost hose(s) (untouched vehicles)
	Golf R	16	All	All	Turbo Failure	Customer states noise form the engine/turbo
	Golf/GTI, Golf Sportwagen	15-16	All	All	Fuel Level Sensor	Fuel gauge not reading full after topping up the fuel (untouched vehicles)
	Golf/GTI, Golf Sportwagen	16	All	All	Fuel Line Noise	Fuel line rattle from below the vehicle (untouched vehicles after VIN GM016333)
	CC	16	2.0T (CCTA , CBFA)	All	MIL-on P0101 P0100	MIL-on P0101 and/or P0100 with corrosion at the mass air connector terminals
	Golf, Golf Sportwagen	15-16	1.8T (CXBB)	09G AQ250 (6 speed Auto)	EPC Light P03AF P03A5 P03B9 P039B	EPC light on with one or more of P03AF, P03A5, P03B9, P039B (untouched vehicles only in Southeast MI and Los Angeles CA)
Chassis	GTI	16	All	Standard	Clutch Pedal Noise	Clutch pedal squeal/squeak when operating clutch pedal
	Passat	15-16	All	All	Center Cap	Center cap missing after PDI (more than 100 miles on the vehicle)
Electrical	Jetta	16	All	All	Back-up Camera	Back-up camera inoperative (untouched vehicles)
Body	Passat	16	All	All	Instrument Panel Noise	Instrument panel noise (untouched vehicles after VIN HC011431)
	Passat	16-17	All	All	Door Noise	Door(s) noise (untouched vehicles after VIN GC052150)