

On-car analysis list from September 14th, 2016
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Tiguan	15	All	All	MIL-on P013E	MIL-on fault P013E in the ECM
	Passat	16	1.8T (CPRA, CPKA)	All	MIL-on P0299	MIL-on with loose boost hose(s) (untouched vehicles)
	Golf R	16	All	All	Turbo Failure	Customer states noise form the engine/turbo
	Golf/GTI, Golf Sportwagen	15-16	All	All	Fuel Level Sensor	Fuel gauge not reading full after topping up the fuel (untouched vehicles)
	Golf/GTI, Golf Sportwagen	16	All	All	Fuel Line Noise	Fuel line rattle from below the vehicle (untouched vehicles after VIN GM016333)
	CC	16	2.0T (CCTA , CBFA)	All	MIL-on P0101 P0100	MIL-on P0101 and/or P0100 with corrosion at the mass air connector terminals
Chassis	GTI	16	All	Standard	Clutch Pedal Noise	Clutch pedal squeal/squeak when operating clutch pedal
	Passat	15-16	All	All	Center Cap	Center cap missing after PDI (more than 100 miles on the vehicle)
Electrical	Jetta	16	All	All	Back-up Camera	Back-up camera inoperative (untouched vehicles)
Body	Passat	16	All	All	Instrument Panel Noise	Instrument panel noise (untouched vehicles after VIN HC011431)
	Passat	16-17	All	All	Parking Sensor	Parking Sensor Loose or Missing from Front/Rear Bumper
	Passat	16-17	All	All	Door Noise	Door(s) noise (untouched vehicles after VIN GC052150)