

Check Engine Light Illuminated with Stored Fault Code P008700 in ME Control Unit N3/34 and or P008A00 in FSCU N118

Topic number	LI47.00-N-067942
Version	1
Function group	47.00 General
Date	03-26-2018
Validity	Metris 447
Reason for change	
Reason for block	

Complaint:

Check engine light illuminated in Instrument Cluster.

Cause:

FSCU software requires update.

Remedy:

1.) No parts need to be replaced.

2.) Please follow the guided tests for fault code P008700 and P008A00. The SW for the FSCU has to be updated; not the ME CU SW.

3.) Ensure guided tests are being performed with Xentry DVD 09/2017 with AddOn 8873 / DVD 12/2017 with AddOn 8874 or Newer.

Validity		
Vehicle	Engine	Transmission
*	274.920	*
Vito/Metris 447 - 447.603	*	*
Vito/Metris 447 - 447.703	*	*