

On-car analysis list from May 5th, 2015
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta, Jetta SW, Golf, Beetle, Beetle Conv, Passat	14	2.0TDI CJAA / CKRA	All	EGR Valve	Mil-on with fault code P046C, untouched vehicles
	Jetta, Golf, Passat	15	2.0TDI CVCA/CRUA	All	Oil Light	Customer states the oil light is on
	Tiguan	10 - 13	2.0T CCTA/CBFA	All	Cat Converter	Fault code P0420 stored with no Mil-on (usually found during GFF scan)
	Jetta Hybrid	13 - 15	All	All	P309F and P309D Fault Code	Mil-on no electric drive mode, untouched vehicles
	Jetta, Passat, Beetle, Beetle Conv	14-15	1.8T (CPRA, CPKA) 2.0T (CPPA, CPLA)	All	Map Sensor	Mil-on with fault code P0068 and/or P1158, untouched vehicles
	Passat	12-13	3.6L (CDVB)	All	Cat Converter	Mil-on with fault code P0420 and P0430, untouched vehicles (Must contain both faults)
	Tiguan	12-15	All	All	P2015 in ECM	Mil-on with fault code P2015, untouched vehicle, with mileage between 10K and 30K, customer willing to have drive recorder installed
Electrical	Beetle, Beetle Conv	14-15	All	All	Front Turn Signal Bulb Loose or Uninstalled	Turn signal indicator blinks fast; bulb is found loose or uninstalled on either side, untouched vehicles.
	Passat	14-15	All	All	Backup Camera Inoperative	Backup camera is completely inoperative (static)
	Passat	15	All	All	High Beam Bulb	High beam bulb is burned out on one side (untouched headlamp)
	Beetle Conv	14- 15	All	All	Interior Light Rattle	Interior map light rattles while driving
Chassis	Golf, GTI	15	Gasoline	All	Rear Brake Noise	Rear brake squeal when stopping (untouched vehicles)
	GTI	15	All	All	Pedal Vibration	Brake pedal pulsation and/or steering wheel vibration when braking (untouched vehicles)