



Technical Service Bulletin

01 MIL on, DTC P203B00 stored in the ECM - TDI clean diesel only

01 18 75 2035368/6 June 12, 2018. Supersedes Technical Service Bulletin Group 01 number 15-35 dated July 29, 2015 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2013 - 2014	All	TDI clean diesel
A6, A7, and Q5	2014 - 2016	All	TDI clean diesel

Condition

REVISION HISTORY		
Revision	Date	Purpose
6	-	Revised title Revised <i>Service</i> (Added Note) Revised <i>Warranty</i> (Updated Labor Operations and added Claim Types)
5	07/30/2015	Revised header data (Added models) Revised <i>Technical Background</i> (Completely revised) Revised <i>Service</i> (Completely revised) Revised <i>Warranty</i> (Added time for software update; updated TU)
4	12/18/2014	Revised <i>Warranty</i> (Updated Labor Operations)

Customer states:

- MIL on

Workshop findings:

The following DTC is stored in the engine control module (ECM), J623 (address word 0001):

- **DTC P203B00** (Reductant Level Sensor Circuit Range/Performance)

Technical Background

Diagnostic software in the control unit for reduction agent metering system, J880 (address word 00AC), has been optimized to avoid this fault. In some cases, the AdBlue level sensor may still require replacement.

Improved level sensor and level sensor diagnostics.



Technical Service Bulletin

Production Solution

Improved level sensor and level sensor diagnostics.

Service

Update the parameters:

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the parameters of the control unit for reduction agent metering system, J880 (address code 00AC), using SVM code **ACA001**.

3. If the fault code P203B00 is stored with the symptom code (DFCC) 65540 or 65541 (Figure 1), replace the reduction agent level sensor (delivery unit) in addition to updating the parameters. Follow the instructions in the Elsa Repair Manual (*Engine >> 6-cylinder TDI Common Rail Engine (Gen II) >> 26 Exhaust System, Emission Controls, Selective Catalytic Reduction System*).



Note:

If the DTC and symptom code are not stored in the ECM exactly as in Step 3, this TSB does not apply.

☐ Ereignisspeichereinträge:

DTC memory entry	
Number :	P203B00: Reductant Level Sensor Circuit Range/Performance
Error type 2 :	passive/sporadic
Symptom :	16925
Status :	10101000

☐ Standard ambient conditions:

Date :	6/19/14
Time :	10:41:55 AM
Mileage (DTC) :	4460
Priority :	2
Frequency counter :	254
Elimination counter / driving cycle :	255

Figure 1. Location of symptom code.

Do not contact TAC unless the problem persists after the software/hardware update or if there is a problem with the SVM process.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only.
Service Number:	2683
Damage Code:	0040



Technical Service Bulletin

Labor Operations:	For A8:		
	Reductive agent tank remove + reinstall	2681 1900	130 TU
	Reductive agent supply module remove + reinstall	2683 1950	30 TU
	Reductive agent inspect + add	2688 3550	30 TU
	For A6 and A7:		
	Reductive agent tank remove + reinstall	2681 1900	110 TU
	Reductive agent supply module remove + reinstall	2683 1950	20 TU
	Reductive agent inspect + add	2688 3550	10 TU
	For Q5:		
	Q5 reductive agent tank remove + reinstall	2681 1900	90 TU
	Q5 reductive agent supply module remove + reinstall	2683 1950	30 TU
	Reductive agent inspect + add	2688 3550	10 TU
	For all vehicles:		
	Software update	2360 2599	50 TU
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 80 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2035368/6		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
G 052910A4	Urea solution AdBlue	As needed (Max 3)
4G0131969E	A6/A7/A8 Delivery unit for reduction agent metering system	1
8R0131969D	Q5 Delivery module for urea solution AdBlue	1

Additional Information

All parts and service references provided in this TSB (2035368) are subject to change and/or removal. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.