

On-car analysis list from November 14th, 2016
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Tiguan	15	All	All	MIL-on P013E	MIL-on fault P013E in the ECM
	Golf R	16	All	All	Turbo Failure/MIL-on Misfire Faults	Customer states noise from the engine/turbo and/or MIL-on and misfire faults
	Golf/GTI, Golf Sportwagen	15-17	All	All	Fuel Level Sensor (10/11/2016)	Fuel gauge reading lower than actual fuel level (untouched vehicles) (can not have had Recall 20Y6 performed)
	Tiguan, EOS, CC	16-17	All	All	Rear Main Seal Leak	Customer states oil leak (untouched vehicles)
	Passat	14-17	1.8T (CPKA/CPRA)	All	MIL-on P2407	MIL-on fault P2407 in the ECM (untouched vehicles)
	Tiguan, CC	2017	2.0T (CCTA/CBFA)	All	MIL-on P0016	MIL-on fault P0016 in the ECM
	Golf/GTI, Golf Sportwagen	16-17	All	All	Fuel Line Noise	Fuel line rattle from below the vehicle (untouched vehicles after VIN GM016333)
Chassis	GTI	16	All	Standard	Clutch Pedal Noise	Clutch pedal squeal/squeak when operating clutch pedal
	Passat	15-16	All	All	Center Cap	Center cap missing after PDI (more than 100 miles on the vehicle)
Body	Passat	16	All	All	Instrument Panel Noise	Instrument panel noise (untouched vehicles after VIN HC011431)
	Beetle, Beetle Conv.	16-17	All	All	Window Regulator	Front window glass contacts rear window glass
	Passat	16-17	All	All	Parking Sensor	Parking Sensor Loose or Missing from Front/Rear Bumper
	Passat	16-17	All	All	Door Noise	Door(s) noise (untouched vehicles after VIN GC052150)