

On-car analysis list from October 14th, 2016
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Tiguan	15	All	All	MIL-on P013E	MIL-on fault P013E in the ECM
	Golf R	16	All	All	Turbo Failure	Customer states noise from the engine/turbo
	Golf/GTI, Golf Sportwagen	15-17	All	All	Fuel Level Sensor (10/11/2016)	Fuel gauge not reading full after topping up the fuel (untouched vehicles) (MUST have any of P0461/2/3 and/or B103E1A/B in ECM or Instrument cluster)
	Tiguan, EOS, CC	16-17	All	All	Rear Main Seal Leak	Customer states oil leak (untouched vehicles)
	Golf/GTI, Golf Sportwagen	16-17	All	All	Fuel Line Noise	Fuel line rattle from below the vehicle (untouched vehicles after VIN GM016333)
Chassis	GTI	16	All	Standard	Clutch Pedal Noise	Clutch pedal squeal/squeak when operating clutch pedal
	Passat	15-16	All	All	Center Cap	Center cap missing after PDI (more than 100 miles on the vehicle)
Body	Passat	16	All	All	Instrument Panel Noise	Instrument panel noise (untouched vehicles after VIN HC011431)
	Passat	16-17	All	All	Parking Sensor	Parking Sensor Loose or Missing from Front/Rear Bumper
	Passat	16-17	All	All	Door Noise	Door(s) noise (untouched vehicles after VIN GC052150)