

October 4, 2018

Version 2

MIL Comes On with DTC P100C and/or P0010

This bulletin is replaced by S/B 18-089, Product Update: 2018 Clarity Plug-In Hybrid EVTC & 3-Way Valve Software Update (P100C/P0010/P26A3)

If you did Service Bulletin 18-079 on or before October 4th, 2018, use the Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
1225A0	Update the PCM software.	0.2 hr	03214	03203	A18079A	37805-5WJ-A61

Skill Level: Repair Technician

END

CUSTOMER INFORMATION:The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.