TECH TIP: DTC P0455 on Sorento(XMa)

NUMBER: TT051	MODEL: 2012 Sorento (XMa) w/2.4L Engine	DATE: 02/04/2014

Symptom: I have a 2012 Sorento with a 2.4L engine that is setting a P0455 DTC. What do I do next?

Repair: Test the functionality of the PSV (purge solenoid valve) and monitor EVAP test results / CARB readiness monitors and replace / repair, as necessary.

Note: Tech Tips are not a substitute for proper diagnosis.