Bulletin No.: PIC5890

Date: Jul-2013

Service Bulletin

PRELIMINARY INFORMATION

Subject: **Folding Top Inoperative DTC B3680 Symptom 01**

Models: **2013 Chevrolet Camaro Convertible**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may comment the folding top is inoperative. This may be an intermittent concern. The DTC B3680.01 (DTC B3680 Symptom 01) will be stored as current or history, depending on whether or not the condition is present.

Recommendation/Instructions

Important: Do NOT replace the folding top pump motor OR the Folding Top Control (FTC) module for this condition. While this may make the concern go away temporarily, it may not cause a permanent correction.

Engineering has developed a new calibration to correct this concern. Reprogram the FTC module following the SI procedure for Folding Top Control Module Programming and Setup.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
*2880068	Folding Top Control Module Programming and Setup	0.4
* This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.		

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION