Bulletin No.: PIP5469A
Published date: 06/20/2017

Preliminary Information

PIP5469A Check Engine Light On With DTC P10D1

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2017	All	All	6.6 L5P	All
GMC	Sierra	2017	All	All	6.6 L5P	All

Involved Region or Country	North America
Additional Options (RPO)	L5P
Condition	Some customers may comment on a Service Engine Soon Light / Check Engine Light that occurred once and did not persist beyond one key cycle. Technicians may find DTC P10D1.

Correction:

A revised calibration has been released to address this condition. Please refer to bulletin 17-NA-171.

Version History

Version	2
Modified	6/5/2017 to refer to bulletin 17-NA-171.

© 2016 General Motors. All Rights Reserved.