Bulletin No.: PIP5470A
Published date: 06/20/2017

Preliminary Information

PIP5470A Check Engine Light On With DTC P054F

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2WD	2017	All	All	6.6 L5P	All
Chevrolet	Silverado 4WD	2017	All	All	6.6 L5P	All
GMC	Sierra 2WD	2017	All	All	6.6 L5P	All
GMC	Sierra 4WD	2017	All	All	6.6 L5P	All

Involved Region or Country	**North America**
Additional Options (RPO)	**6.6 L5P**
Condition	**Some customers may comment on a Service Engine Soon Light / Check Engine Light. Technicians may find DTC P054F.**

Correction:

A revised calibration has been released to address this condition. Please refer to bulletin 17-NA-171.

Version History

Version	**2**
Modified	**6/5/2017 To update correction to refer to bulletin 17-NA-171.**

© 2016 General Motors. All Rights Reserved.