

Technical Service Bulletin



19 MIL on; DTC related to coolant pump is stored in ECM (P261A00, P261B00, P261C00)

19 16 66 2043142/1 January 27, 2016.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2012 - 2016	All	CAE* and CPM* engines only

Condition

- MIL sporadically on.
- One or more of the following DTCs is stored in the engine control module (ECM), J623 (address word 01):
 - **DTC P261A00** (Coolant Pump “B” Control Circuit/Open)
 - **DTC P261B00** (Coolant Pump “B” Control Circuit Range/Performance)
 - **DTC P261C00** (Coolant Pump “B” Control Circuit Low)

Technical Background

The continued coolant circulation pump sporadically fails.

Production Solution

Not applicable.

Service

1. Confirm that one or more of the DTCs listed in the *Condition* are stored.
2. Replace the auxiliary coolant pump (part number 059121012B) with the updated part (part number 06D121601). Use the bracket with part number 06H121079N.

Technical Service Bulletin



Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	1945		
Damage Code:	0040		
Labor Operations:	Auxiliary coolant pump remove+reinstall	1945 1913	70 TU
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 30 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2043142/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
06D121601	Additional water pump	1
06H121079N	Bracket for additional water pump	1

Additional Information

All parts and service references provided in this TSB (2043142) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.