



Tech Tips

TT 26-16-02

Date: March 18, 2016

**2015-2016 Passat – DTCS P0442 and/or P0457-Loose Evap
Lines at Canister**

For fault codes P0442 and/or P0457, ensure all connections to charcoal canister are properly secured regardless of test plan results. Please note that if the ECM does not have these faults, this tech tip does not apply.