



Tech Tips

TT 20-13-01

Date: March 8, 2013

**2000-2014 All Vehicles except Routan – ECM Fault P1250
“Fuel Level Too Low” Will Not Clear**

October 10, 2014: Update to model year.

To clear static ECM fault P1250 “Fuel Level Too Low”, add fuel to vehicle and complete a road test of at least 10 miles. Simply adding fuel without completing a road test may not allow fault to clear.