On-car analysis list from October 8th, 2014
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta, Jetta SW, Golf, Beetle, Beetle Conv, Passat	14	2.0TDI CJAA / CKRA	All	EGR valve	Mil-on with fault code P046C, untouched vehicles
	Tiguan, CC, GTI	11 - 12	2.0T CCTA/CBFA	All	High pressure pump	Mil-on P0087 ONLY, with no diagnoses done. If high pressure pump does not click with key on/engine off, contact the VW helpline
Body	Jetta, Passat	14 - 15	All	All	Car -Net Button	Car-Net button fell into the overhead console housing
	Beetle, Beetle Convertible	14 - 15	All	All	Front door window regulator VIN Range Beetle: EM6358465 to FM800000; Beetle Convertible: EM809087 to FM900000	Front door window hits rear window glass (Un-touched vehicles only)
	Jetta	14	All	All	Front windows binding during operation causing false pinch protection activation. VIN range EM236581 to EM350000 or EM386721 to EM500000	Front window(s) binding / Windows roll back down once reaching the top of travel
Electrical	Golf, GTI	15	All	All	HID headlamp w/ LED type DRL inoperative ONLY	Customer states the LED daytime running light strip does not light up
	Jetta	14 - 15	All	All	Horn activation on it's own	Customer states the horn beeps on it's own when driving/turning the steering wheel
Chassis	All (Excluding Routan)	14	All	All	Wheel Center Cap Loose / Fell Off	Customer or technician notices wheel center caps fell off / are loose or the center cap tabs are cracked/broken. Limited to part number: 3B7601171 XRW