8/31/16 MY16 D2, DD, DF, DJ, DP

GPOP - Issue Review System

Part Number: 05175565A$, 68210105A$

Part Description: High Pressure Connector Tube/Fuel Injector

Issue Description: For 2016 6.7 Cummins - When replacing Fuel Injector for a Misfire Code (P0300-P0306), please also replace the High Pressure Connector Tube and return tube with the injectors.

~_____
_~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.