Technical Service Bulletin

01 MIL on (DTC P169A00 - "Loading mode active")

01 14 53 2026483/2 January 8, 2014. Supersedes Technical Service Bulletin Group 01 number 11-23 dated May 23, 2011 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7	2012	All	3.0 TFSI

Condition

REVISION HISTORY		
Revision	**Date**	**Purpose**
2	-	Revised header data (Added customer codes) Revised *Technical Background* (Added description)
1	5/23/2011	Initial publication

- MIL on.
- The following DTC is stored in the engine control module, J623 (address word 01):
  - **DTC P169A00** (Loading mode active)

Technical Background

The vehicle is in transport mode.

Production Solution

Not applicable.

Service

1. Deactivate transport mode through GFF.
2. After transport mode is deactivated, but while still in GFF, turn the ignition off for 20 seconds.
3. Turn ignition on again. Ensure that DTC is deleted and that the MIL is off.

Warranty

This TSB is informational only and not applicable to any Audi warranty

© 2014 Audi of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Additional Information

All parts and service references provided in this TSB (2026483) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2014 Audi of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.