



Tech Tips

TT 19-12-01

Date: January 27, 2012

2009-2015 EOS, Jetta, GTI, Passat, Tiguan with 2.0L TSI
(CCTA, CBFA) – Radiator Identification Sensor -G611-

June 19, 2015: Update to model year applicability.

On TSI (2.0L CCTA, CBFA) equipped vehicles with fault code P2568 Direct Ozone Reduction Catalyst Temperature Sensor, this fault refers to - G611- as Radiator Identification Sensor. If the radiator requires replacement on any above listed vehicle, the -G611- will be packaged separately within the radiator packaging. The new sensor will need to be bonded to the radiator. Use AMV 195 KD101 adhesive (refer to ETKA for latest part number) to bond the sensor.