

On-car analysis list from May 4th, 2017
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Passat	14-17	1.8T (CPKA/CPRA)	All	MIL-on P2407	MIL-on fault P2407 in the ECM (untouched vehicles)
	Passat	13	3.6L (CDVB)	All	MIL-on P0420 and/or P0430	MIL-on P0420 and/or P0430 in the ECM (untouched vehicles)
	Touareg	16-17	All	All	Coolant leak from coolant pump	Coolant leak from the coolant pump (untouched vehicles)
	Passat, Beetle, Jetta, Golf/GTI, Sportswagen	15-17	1.8T & 2.0T EA888 Gen 3	All	Oil pressure warning with P164D	Oil pressure warning with P164D in the ECM (Must have fault in the ECM) (No oil must be present in connector)
Chassis	Jetta	16-17	All	All	Rear Brake Caliper	Rear brake noise, dragging, excessive dust (untouched vehicles)
	Jetta	17	All	All	Brake Hissing	Hissing noise when pressing the brake pedal (untouched vehicles)
Body	Passat	16	All	All	Instrument Panel Noise	Instrument panel noise (untouched vehicles after VIN HC011431)
	Passat	16 - 17	All	All	Trunk latch (release) inoperative	Trunk latch will not release with key fob, button in the door, on the trunk or with easy open feature (foot release).
	Jetta, Beetle	16 - 17	All	All	A/C Inoperative	A/C inoperative, compressor found to be locked up (compressor has to be seized) (untouched vehicles)
	Golf/GTI	16 - 17	All	All	Sunroof Water Leak	Sunroof leaking water after TB has been performed (TB 601701 2045403 MUST have previously been performed)
	Passat	16-17	All	All	Door Noise	Door(s) noise (untouched vehicles after VIN GC052150)
Electrical	Passat, Jetta, Golf/GTI, Golf Sportswagen	17	All	All	KESY Start Concerns	Keyless faulty/Keyless defective error messages with fault(s) B117213/B117313/B117413
	Golf R	17	All	All	Adaptive Cruise Fault	Error message in MFI with fault code C110300 in Address 13