Tech Tips

TT 87-13-01 **Date: June 7, 2013**

2013 Jetta Hybrid – A/C Inoperative, Fault B109EF0 "A/C compressor first run not performed"

If fault B109EF0 "A/C compressor first run not performed" is found in AW 08 A/C/heating Electronics, resolve fault by completing test plan "A/C compressor first run". Test plan is available in VAS PC GFF through Function/Component selection or in ODIS 1.2.0 or later using the "Select self test" button on the Test plan tab.

© 2013 Volkswagen Group of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.