GPOP - Issue Review System

Part Number: 68651399A$

Part Description: FUSE BLOCK - PWR DISTRIBUTION

Issue Description: 1) False fails on PCR, DBSM and PDCs Stuck Closed or open diagnostics, DTC P2AF5 or P2AF6, leading to NTF and unnecessary replacements. Current controls are not robust against depleted auxiliary battery condition. Please follow SOL S2508000031. 2) A/C Blowing hot air or not working. A/C relay clutch not operating, dealers are unnecessary replacing PDCs. Battery disconnection is required to reset PCM. Please follow SOL S2624000004.