

CAD 25-4049 Illuminated MIL With DTCs in the GSM




2023 F-150
Settings - Privacy and security
wwwqa.fordtechservice.dealerconnection.com
2023 F-150
1FTFW1E80PKF06701 - FDRS Support
Professional Technician System
Welcome mthakkil
Help
Logout
PTS 2.0 Beta
New
Home
Vehicle ID
Diagnostics
Connected Vehicle
TSB/GSB/SSM
Workshop
Wiring
PC/ED
Service Tips
Owner Info
PDI
SLTS
Submit Global Concern Report (GCR)
Cloud Assisted Diagnostics (CAD)
3. If DTC P0606 cannot be cleared, replace the GSM.
Parts
Part Name
Base Part #
N/A
N/A
Warranty Claiming Details
• When submitting warranty claims for CAD Repairs, document the CAD Number, Causal Part #, Condition Code, and any appropriate CAD Labor Operation Codes on the Repair Order.
• Coverage of parts and labor is subject to the provisions of New Vehicle Limited Warranty, Service Part Warranty and Extended Service Plan coverage.
• The information displayed for this Cloud Assisted Diagnostic is only applicable to DTCs shown in the table. Address all other DTCs and customer concerns independently. The advanced diagnostic information displayed is from connected vehicle data and it may not match current DTC(s) if a self-test is performed.
Casual Base Part Number:
N/A
Condition Code
N/A
Labor Operation
Operation No.
Labor Time
N/A
N/A
N/A
Important Notices & Disclaimers:
* Predictions and Repair instructions may utilize AI Machine Learning.
* CAD repair directions are only available on vehicles with connected and authorized vehicle modems.
* To learn more or enroll in Predictive Repair Intelligence (PRI), Click Predictive Repair Intelligence (PRI)
Close
© Copyright 2000, 2001-2026, Ford Motor Company. All rights reserved
Privacy
Contact Us
US- USA- DEALERS-EN-US
22°
2:05 PM
10/29/2026