



Service Bulletin

PRELIMINARY INFORMATION

Subject: Post Catalyst Fuel Trim System High Limit DTC P2097

Models: 2013 Chevrolet Malibu
Equipped with LCV 2.5 L VIN code A

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some 2013 Malibu's may set an intermittent DTC P2097.

The post o2 sensor has reached the limit of how much enrichment it can control.

This is because the sensor is sensing the exhaust stream is on the lean side

Recommendation/Instructions

Check freeze frame/ failure records to determine what the short term/ long term fuel trims were when the DTC set.

If the fuel trims were adding fuel (positive counts above 5) then it's possible that there is:

- an intake system leak, check hoses and lines
- non OEM/ quality air filter
- low/ restricted flow injectors, check the flow and if on low side, use an injector cleaner and retest to see if flow is improved/ even cylinder to cylinder.

If the fuel trims are normal (+/- 3) when the DTC is set

- Check that the post o2 sensor heater and circuit are working
- Check for exhaust system leaks, can use evap tester to pressurize exhaust system and spray a soapy solution around the exhaust system joints looking for leaks.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION