



Preliminary Information

PIP5469 Check Engine Light On With DTC P10D1

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2017	All	All	6.6 L5P	All
GMC	Sierra	2017	All	All	6.6 L5P	All
Involved Region or Country		North America				
Additional Options (RPO)		L5P				
Condition		Some customers may comment on a Service Engine Soon Light / Check Engine Light that occurred once and did not persist beyond one key cycle.				
Cause		Upon inspection technicians will find DTC P10D1 set.				

Correction:

Complete the current SI diagnostic for any trouble codes or symptoms found.
If the diagnostics are inconclusive and this is the first occurrence of this condition on this vehicle, the MIL can be cleared and the vehicle returned to the customer.
GM Engineering is aware of this concern and is working on a resolution.
This Preliminary Information will be updated when further information is available.

Version History

Version	1
Modified	

