



Preliminary Information

PIP5470 Check Engine Light On With DTC P054F

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2WD	2017	All	All	6.6 L5P	All
Chevrolet	Silverado 4WD	2017	All	All	6.6 L5P	All
GMC	Sierra 2WD	2017	All	All	6.6 L5P	All
GMC	Sierra4WD	2017	All	All	6.6 L5P	All
Involved Region or Country	North America					
Additional Options (RPO)	6.6 L5P					
Condition	Some customers may comment on a Service Engine Soon Light / Check Engine Light on.					
Cause	Upon inspection technicians will find DTC P054F set.					

Correction:

Complete the current SI diagnostic for any trouble codes or symptoms found. If the DTC P054F is no longer active and this is the first occurrence of this condition on the vehicle, the MIL can be cleared. GM Engineering is aware of this concern and is working on a resolution. This Preliminary Information will be updated when further information is available.

Version History

Version	1
Modified	

