



Preliminary Information

PIC5492F Diagnostic Tip: Diagnosing Vehicles with OnStar DTC B101D-37

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
All	All	2011 - 2018	All*See Note 1	All*See Note 1	All	All
All	All	2000 - 2015	All*See Note 2	All*See Note 2	All	All

Note 1 2011-2018 GM Passenger Cars & Light Duty Trucks with OnStar (RPO UE1)
Note 2 2000 - 2015 Canada GM Passenger Cars & Trucks with Canada Upgrade (latest version of Bulletin [15-08-44-001](#))

Supersession Statement

This PI was superseded to update Model Years Please discard PIC5492E.

Condition / Concern

While diagnosing a vehicle with an OnStar concern, technicians may find history DTC B101D-37 in the OnStar VCIM while checking for codes.

Recommendations / Instructions

Engineering has determined that this code will only display in history on the scan tool and will not cause issues with OnStar system operation. Dealers are to disregard this history DTC and address symptoms as described by the customer, including any additional codes that may be current.

