

	GROUP Fuel	MODEL 2017MY Cadenza (YG)
	NUMBER PS567	DATE July 2018
 TECHNICAL OPERATIONS		
SUBJECT: DTC P0456/P0442 WITH FUEL PUMP SEAL DAMAGE		

This Pitstop provides information regarding DTC P0456/P0442 (Evaporative Emissions System – (Very) Small Leak Detected) or fuel smell on some 2017MY Cadenza (YG) vehicles. When addressing the concern with DTC P0456/P0442 and the vapor lines, fuel cap, and all other corresponding circuits are found to be within specifications, it may be necessary to inspect the fuel pump seal for damage. If this seal is found to be torn or split, replace the fuel pump seal by referring to the “Engine Control / Fuel System → Fuel Delivery System → Low Pressure Fuel Pump → Repair procedures” chapter in the applicable Shop Manual on KGIS.

