



Preliminary Information

PIT5696 ABS / TCS MIL On Code B0010.5A Stored

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Envision	2018 - 2019	All	All	All	All
Chevrolet	Colorado	2018 - 2019	All	All	All	All
Chevrolet	Equinox	2018 - 2019	All	All	All	All
GMC	Canyon	2018 - 2019	All	All	All	All
GMC	Terrain	2018 - 2019	All	All	All	All

Involved Region or Country:	North America
Condition:	ABS / TCS MIL on , Code C0010.5A stored in EBCM. Possible OnStar notification.
Cause:	Engineering is looking into the cause of this code . There currently have been no cases of a functional concern regarding this code so if the C0010.5A is stored alone , clear the code and road test . If the C0010.5A is stored with other communication or component codes diagnose those codes.

Correction:

If the code C0010.5A is the only code stored clear the code and road test , engineering is investigating the cause.

Version History

Version	1
Modified	06/28/2019 - Created on



GENERAL MOTORS