



NUMBER: 09-002-19

GROUP: 09 - Engine

DATE: May 1, 2019

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This Service Bulletin is also being released as Rapid Response Transmittal (RRT) 19-035, dated May 01, 2019. All applicable Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the Un-Sold vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library.

SUBJECT:

Diesel Low Pressure Exhaust Gas Recirculation (EGR) Valve Cleaning

OVERVIEW:

This bulletin involves cleaning the diesel low pressure EGR valve.

MODELS:

2019 (JL) Jeep Wrangler

NOTE: This bulletin applies to vehicles within the following markets/countries: EMEA.

NOTE: This bulletin applies to vehicles built on or before January 31, 2019 (MDH 0131XX) equipped with a 2.2L N-S I4 Turbo Diesel W/ESS (Sales Code EBH).

SYMPTOM/CONDITION:

Vehicles may display a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find that the following Diagnostic Trouble Code (DTC) has been set:

- P045E - EGR -B- Control Stuck Open.

DIAGNOSIS:

If the VIN is listed in VIP or your RRT VIN list, perform the repair. **This RRT only applies to vehicles on the RRT VIN list.**

REPAIR PROCEDURE:

1. Verify the ambient temperature is above 0° C (32° F).
2. Using wiTECH, record all DTCs and clear them.
3. Start the engine and allow it to run until the coolant temperature reaches a minimum of 50° C (122° F). Monitor the coolant temperature using wiTECH.

NOTE: Do not leave the ignition off for more than 30 seconds to avoid the engine cooling down.

4. Turn the ignition **off** for 10 to 30 seconds.
5. Turn the ignition **on** for 10 to 20 seconds to allow the low pressure EGR to perform several opening and closing cycles.
6. Turn the ignition **off** for 10 to 30 seconds.
7. Repeat steps 4 through 6 for a total of **nine times**.
8. Did the MIL illuminate and **DTC P045E** set, after the above cleaning procedure was performed?
 - YES>>> Follow normal diagnostic procedures for the DTC and repair as necessary per current warranty guidelines.
 - NO>>> This bulletin has been completed.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
25-01-45-9C	Clean EGR Valve - 2.2 Liter Diesel Engine Only (2 - Skilled)	10 - Diesel	0.5 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------