

Subject: MSP66 - ENGINE WARNING ILLUMINATION WITH DTC P0DAB - 2024-2026 CX-90 AND 2025-2026 CX-70	Campaign No.: MSP66 Last Issued : 12/11/2025
--	---

DESCRIPTION

ATTENTION ALL MAZDA DEALERS. PLEASE SEE BELOW FOR THE ENTIRE DEALER ANNOUNCEMENT BEING SENT DECEMBER 15, 2025 AND REPAIR PROCEDURE UPDATED TUESDAY DECEMBER 16, 2025.

WARRANTY CLAIMS CAN NOW BE SUBMITTED, PLEASE SEE UPDATED PROCEDURES BELOW.

Dear Mazda Dealer Colleagues,

Mazda Motor Corporation has decided to conduct a Mazda Service Programs (MSP66) for vehicles in the U.S. and U.S. Territories. Mazda vehicles sold in Canada and Mexico are also affected by this program and must be repaired if presented to your dealership. All vehicles in this program will be in "Open" status on December 15, 2025 concurrent with the announcement of this communication.

MAZDA SALES AND SERVICE TEAMS - ACTION ITEM: There are approximately 7,000 vehicles in stock at U.S. Mazda dealers which must be repaired prior to delivery. All Mazda dealers must quarantine any affected new, used or Certified Pre-Owned in-stock vehicles until the repair is completed. Once completed, the car can be delivered, and the Warranty claim can be submitted later without penalty since the car has been repaired. The affected dealer list will be provided to your District Service Manager daily beginning with receipt of this dealer email.

Subject Vehicles MSP66

Model	Subject VIN range	Subject production date range
2024-2026 MY CX-90 H3T M Hybrid Boost	JM3KK**** R1 100044 - 189861 JM3KK**** S1 189862 - 261073 JM3KK**** T1 350010 - 367752	From December 27, 2022 through November 17, 2025
2025-2026 MY CX-70 H3T M Hybrid Boost	JM3KJ**** S1 100014 - 134448 JM3KJ**** T1 200004 - 202573	From December 5, 2023 through November 17, 2025

Production Note: Only the vehicles in these above ranges and with an "OPEN" status for MSP66 in the

Page 1 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Vehicle Inquiry Screen are affected.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.